

**Kiribati - Northern Line Group - Kiritimati Atoll
— Lagoon; buoys**

230

Paragraph 9.53 including heading *Replace by:*

Anchorage and harbours

Lagoon

9.53

1 The lagoon is generally very shallow and navigation is difficult even for boats. Currents may attain rates of 4 to 5 kn. There is a boat passage, marked by beacons, from London to Saint Stanislas in the SW part of the lagoon.

UKHO; ENC GB50714D (3.000)

[NP62-No 55-Wk 35/24]